





Low Hydrogen Embrittlement (LHE) Zinc-Nickel (Zn-Ni) Qualification Test Result and Process Parameters Development

Dave Frederick, USAF Craig Pessetto, ES3 Steve Gaydos, Boeing

9 February 2011

including suggestions for reducing	completing and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number.	arters Services, Directorate for Infor	mation Operations and Reports	, 1215 Jefferson Davis	Highway, Suite 1204, Arlington		
1. REPORT DATE 09 FEB 2011		2. REPORT TYPE		3. DATES COVERED 00-00-2011 to 00-00-2011			
4. TITLE AND SUBTITLE				5a. CONTRACT	NUMBER		
	abrittlement (LHE)	Qualification	5b. GRANT NUMBER				
Test Result and Pr	ocess Parameters D	evelopment		5c. PROGRAM E	ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER			
				5e. TASK NUMBER			
				5f. WORK UNIT NUMBER			
	ZATION NAME(S) AND AE h Legend Hills Drive	` '	15	8. PERFORMING REPORT NUMB	G ORGANIZATION ER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)			
		11. SPONSOR/MONITOR'S REPORT NUMBER(S)					
12. DISTRIBUTION/AVAIL Approved for publ	LABILITY STATEMENT ic release; distributi	ion unlimited					
	OTES 11: Sustainable Surf Pans, LA. Sponsored		-	Defense Worl	kshop, February 7 -		
14. ABSTRACT							
15. SUBJECT TERMS							
16. SECURITY CLASSIFICATION OF: 17. LIMITATION ABSTRACT				18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON		
a. REPORT b. ABSTRACT c. THIS PAGE unclassified unclassified unclassified		Same as Report (SAR)	53	RESPONSIBLE PERSON			

Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and

Report Documentation Page

Form Approved OMB No. 0704-0188



Technical Objectives



- Small Business Innovative Research (SBIR) Phase I Feasibility Study
- The specific technical objectives of the SBIR Phase II effort are as follows:
 - Successfully pass the following performance parameters, using a prototype tank installation:
 - Installation of a prototype tank for plating demonstration on test coupons and full size components
 - Adhesion
 - Hydrogen Embrittlement
 - Re-embrittlement
 - Liquid and Solid Metal Embrittlement (LME/SME)
 - Fatigue
 - Corrosion
 - Brush Plating for repair of damaged LHE Zn-Ni coatings (Touch Up)
 - Torque Tension
 - Review requirements for Non Destructive Inspection (NDI)
 - Optimize conversion coating
 - Option 1: Develop an accelerated hydrogen embrittlement test procedure :



Prototype Tank Implementation



- ES3 implemented a tank of approximately 325 gallons for the purpose of demonstrating the LHE Zn-Ni plating process on some full sized gear components
- The demonstration tank was used to develop uniform plating thicknesses and process parameters on test coupons and full scale landing gear components
- During the plating operations
 Quality Assurance testing has been conducted to ensure the alkaline LHE Zn-Ni solution is within proper process limits



Dipsol IZ-C17+ LHE Zn-Ni Plating Tank



Prototype Tank Implementation






Tri-Chromium Conversion Coat Tank



Bend to Break Adhesion Test Coupons



- Adhesion of the LHE Zn-Ni coating to the substrate was tested per ASTM B571
- All adhesion test coupons were manufactured from 1"x 4"x 0.040" 4130 steel sheet
- Results: All Test coupons passed



Adhesion Test Coupons



Dipsol™ LHE Zn-Ni Test Panels After Dry and Wet Tape Adhesion Test of Primer





Deft 44-GN-072



Deft 44-GN-098



Dry and Wet Paint Adhesion Test Results per ASTM D3359



Scribed Dry and Wet Tape Adhesion Test Results

4" x 6" x 0.040" 4130 Steel Substrate									
			DRY T	DRY TAPE ADHESION			WET TAPE ADHESION		
PANEL	ID PRETREATMENT	COATING	PERCENTAGE COATING REMOVED	ASTM D 3359	Pass / Fall	PERCENTAGE COATING REMOVED	ASTM D 3359	Pass / Fall [2]	
1			0	5A	Pass	0	4A	Pass	
2	LHE Zn-Ni Plating		0	5A	Pass	2	4A	Fail	
3		Deft	0	5A	Pass	0	5A	Pass	
1	Cd Plated w/	Cr ersion	0	5A	Pass	0	5A	Pass	
2	Hex Cr Conversion		0	5A	Pass	0	5A	Pass	
3	Coating		0	5A	Pass	0	5A	Pass	
4			0	5A	Pass	0	5A	Pass	
5	LHE Zn-Ni Plating		0	5A	Pass	0	5A	Pass	
6		Deft	0	5A	Pass	10	4A	Fail	
4	Cd Plated w/	44-GN-098	0	5A	Pass	0	5A	Pass	
5	Hex Cr Conversion	ion	0	5A	Pass	0	5A	Pass	
6	Coating		0	5A	Pass	0	5A	Pass	

Notes:

Panels immersed in distilled water at room temperature for 24 hours.

- [1]- ASTM D 3359 Criteria:
 - 5A No peeling or removal
 - 4A Trace peeling or removal along incisions
 - 3A Jagged removal along incisions up to 1/16 inch on either side
 - 2A Jagged removal along most of incisions up to 1/8 inch on either side
 - 1A Removal from most of the area of the "X" under the tape
 - 0A Removal beyond the area of the "X"
- [2]- The primer shall show no adhesion failure.



LHE Zn-Ni Hydrogen Embrittlement Testing



- Coupons manufactured per ASTM F519 specifications (4340)
- Coupons plated and tested 28th
 April, 2009 upon initial installment of LHE Zn-Ni demonstration tank
- Additional coupons plated and tested at additional dates
- All coupons tested per ASTM F519 and passed the 200 hour sustained load tests @ 75% of the tensile notch fracture strength




ASTM F519 Type 1A.1 Test Coupons



HE Plated Cross Section








HE Plated Cross Section







LHE Zn-Ni Hydrogen Re-Embrittlement Testing





LHE Zn-Ni Re-Embrittlement Testing Machine

www.ES3inc.com • 1669 E. 1400 S • Clearfield, UT 84015 (801) 926-1150 • fax (801) 926-1155



LHE Zn-Ni Hydrogen Re-Embrittlement Testing



Re Embrittlement Test Matrix							
	Test Solution						
Plating	Distilled Water @ Room Temp Tested 45% NFS for 150Hrs	3.5% Salt Water @ Room Temp Tested 45% NFS for 150Hrs	Diluted Calla 296	Dwg 9825019* Diluted Calla 602 LF Max Temp 160 °F Tested 75% NFS for 200Hrs	Concentrated Calla 296 @ Room Temp tested 45% NFS for 150Hrs	Concentrated Calla 602LF @ Room Temp tested 45% NFS for 150Hrs	
LHE Zn-Ni	Pass	Failed	Pass	Pass	Pass	Pass	
Cadmium	Pass	Failed	Pass	Pass	Pass	Pass	
IVD	Failed	Failed	Not Tested	Not Tested	Not Tested	Not Tested	

^{*}The specimens were immersed in the cleaning compound at the manufacturer's maximum recommended temperature, and appropriate cleaning concentration, for 30 minutes. Removed. Air dried and loaded to 75% NFS for 200Hrs.

Re-Embrittlement results:

•Coupons tested by an ISO 9001 certified facility. Coupons tested IAW ASTM F519.

The coupons tested immersed in solutions of Water, 3.5% Salt Water, Dilute* Calla 296, Dilute* Calla 602LF, Concentrated Calla 296, and Concentrated Calla 602LF.

*NOTE – Dilute means mix cleaning solution to manufacturer's recommended use concentration and heat to manufacturer's maximum recommended use temperature.

Cleaning solutions used in testing were:

Calla 296

Calla 602LF

LHE Zn-Ni performs better than IVD and as well as Cad



Liquid/Solid Embrittlement Testing




- Liquid and Solid Metal Embrittlement (LME and SME) occur when one metal, either as a liquid or solid, intrudes into the structure of another, potentially causing embrittlement in the base metal
- Melting points for the coating metals are as follows:
 - Cadmium ~610°F
 - Zinc ~787°F
 - Nickel ~2650°F

Temp/NFS	Material	LHE Zn-Ni 200Hr	Cad 200Hr	LHE Zn-Ni Step Load	Cad Step Load
600F/85%	300M	Pass	Fail	100% NFS	-N/A-
500F/85%	300M	Pass	Fail	100% NFS	87% NFS
400F/85%	300M	Pass	Fail	100% NFS	91% NFS
400F/75%	300M	Pass	Fail	100% NFS	81% NFS



Liquid/Solid Metal Embrittlement Testing





LHE Zn-Ni and Cad Type 1a.1 Specimens After ISL Test to Determine the NFS After Exposure to 400°F for 200 Hours



Fatigue Testing



- Phase II LHE Zn-Ni fatigue testing is an extension of Phase I work
- Phase II LHE Zn-Ni fatigue testing continues to broaden the data base and increase the statistical validity of the data
- Manufacturing of coupons and Fatigue Testing IAW ASTM E466
 - All coupons were plated per manufacture's plating solution limits






Phase I Fatigue Testing (Shotpeened Coupons)



C-17 P2 Program Fatigue Data (2005)

(IZ-C17 with Hex conversion coating)



www.ES3inc.com ● 1669 E. 1400 S ● Clearfield, UT 84015 (801) 926-1150 ● fax (801) 926-1155






Shotpeened Coupons	Stress L	oads (KSI 180) R= -0.3 200	Total Quantity	
Bare	5	5	5	15	
Cad Plated	5	5	5	15	
Zn-Ni Plated Tri Chrome	5	5	5	15	
Zn-Ni Plated Hex Chrome	5	5	5	15	
*Zn-Ni Plated Atotech Tri Chrome	5	5	5	15	
Zn-Ni Plated Atotech Hex Chrome	5	5	5	15	
Total Fatigue Coupons					
* Bake before Tri CC					




























www.ES3inc.com ● 1669 E. 1400 S ● Clearfield, UT 84015 (801) 926-1150 ● fax (801) 926-1155





- Corrosion tests were conducted on LHE Zn-Ni coupons with cadmium as the baseline
- Testing was also performed on both cadmium and LHE Zn-Ni coated coupons with a prime/paint topcoat after being scribed (See Table below). All test coupons were 4"x 6"x 0.040" 4130 steel sheet
- All testing was performed per ASTM B117
- Test specimens were both scribed and un-scribed



Corrosion Test Matrix

# of steel Panels	Plating	Scribed	Prime/Paint	
3	LHE Zn-Ni	Yes	No	
3	LHE Zn-Ni	No	No	
3	Cd	Yes	No	
3	Cd	No	No	
3	LHE Zn-Ni	Yes	Yes	
3	Cd	Yes	Yes	





Cadmium with Hexavalent Chrome Conversion Coating Unscribed – ASTM B 117

Figure

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected



1000 hours

Test Panel
Removed From
Salt Spray Cabinet –
Excess Amount
of Red Rust
Detected

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected

3000 hours

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected


5000 hours

Cadmium Coatings - Phase II ASTM B 117 Panels @ Boeing Unscribed)





IZ-C17+ Zn-Ni with Trivalent Chrome Conversion Coating Unscribed – ASTM B 117 Figure 4



Zinc Nickel Coatings – Phase II ASTM B 117 Panels @ Boeing (Unscribed)





Conversion Coating **Cadmium with Hexavalent Chrome ASTM B** Scribed –

Figure

C-2

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel
Removed From
Salt Spray Cabinet –
Excess Amount
of Red Rust
Detected

1000 hours

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected

3000 hours

Test Panel Removed From Salt Spray Cabinet – Excess Amount of Red Rust Detected Test Panel
Removed From
Salt Spray Cabinet –
Excess Amount
of Red Rust
Detected

Test Panel
Removed From
Salt Spray Cabinet –
Excess Amount
of Red Rust
Detected


5000 hours

Cadmium Coatings – Phase II ASTM B 117 Panels @ Boeing (Scribed)





IZ-C17+ Zn-Ni with Trivalent Chrome Conversion Coating Scribed – ASTM B 117 Figure 6




Zinc Nickel Coatings – Phase II ASTM B 117 Panels @ Boeing (Scribed)





Cadmium with Hexavalent Chrome Conversion Coating ASTM B 117 9 Scribed Painted

Figure



Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected

Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected

1000 hours

Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected

Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected

3000 hours

Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected

Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected


Test Panel Removed From Salt Spray Cabinet -**Excess Amount** of Red Rust Detected

5000 hours

Cadmium Coatings – Phase II ASTM B 117 Panels @ Boeing (Painted/Scribed)








Zinc Nickel Coatings – Phase II ASTM B 117 Panels @ Boeing (Painted/Scribed)



G 85 SO₂ Corrosion-Cad






www.ES3inc.com • 1669 E. 1400 S • Clearfield, UT 84015 (801) 926-1150 • fax (801) 926-1155



G 85 SO₂ Corrosion-LHE Zn-Ni





www.ES3inc.com • 1669 E. 1400 S • Clearfield, UT 84015 (801) 926-1150 • fax (801) 926-1155



Brush Plating Repair



- In order for a brush LHE Zn-Ni plating to qualify it must pass the following tests:
 - Hydrogen Embrittlement (HE) testing per ASTM F519
 - Bend to break adhesion test per ASTM B571
 - Corrosion testing per ASTM B117
- SIFCO recommended procedures were used to plate several sets of HE type 1a.1 coupons, adhesion coupons, and corrosion coupons, using SIFCO 4018 No Bake LHE Zn-Ni brush plating solution
- Test Results Summary:
 - Passed HE testing
 - Passed adhesion testing on steel and LHE Zn-Ni plated steel
 - Corrosion test performance is excellent






Torque Tension



- Robins AFB Cad plating replacement on threaded fastener and components
 - Typical chart for run on break away test showing Cad vs. LHE Alkaline Zn-Ni






Torque Tension



- Robins AFB Cad plating replacement on threaded fastener and components
 - Typical chart for Torque Tension Test showing Cad vs. LHE Alkaline Zn-Ni with MIL-PRF-83483 Anti-seize grease lubricant





Non-Destructive Inspection (NDI)



- OSHA Permissible Exposure Limits (PELs) for LHE Zn-Ni are high enough, such that, the LHE Zn-Ni plating does not have to be removed during the overhaul process (currently all cadmium plated landing gear components which come into the overhaul facility are stripped and cleaned per OSHA PELs)
- There is no NDI interference due to the LHE Zn-Ni coating itself, consequently we can do the following inspections without removing the LHE Zn-Ni coating:
 - Fluorescence Magnetic Particle Inspection (FMPI)
 - Ultra Sonic Inspection
 - Eddy current
 - X-Ray



Conversion Coating Optimization



- Testing was conducted to determine the optimal conversion coating (CC) (Hexavalent vs. Trivalent) and parameters:
 - Baking before and after conversion coating
 - Hexavalent CC: must be applied after bake
 - Trivalent CC: can be applied before or after bake (process time savings)
 - Paint adhesion performance per ASTM D3359
 - Hex-CC Passed
 - Tri-CC Passed
 - Corrosion performance per ASTM B117
 - Hex-CC Passed
 - Tri-CC Passed (performs slightly better)
 - Hydrogen embrittlement per ASTM F519
 - Hex-CC Passed
 - Tri-CC Passed



Conversion Coating Optimization



- Fatigue Performance per ASTM E466
 - Hex-CC Passed
 - Tri-CC Passed
- Process parameters
 - Submerge in conversion coat solution for 1–2 minutes
- Environmental concerns
 - DoD is currently trying to eliminate Hex-CC use
- Recommend Trivalent CC



Development of an Accelerated HE Test



- Accelerated HE Test Development
 - Necessary to production process
 - Accelerated results in < 24 hours
 - Must correlate to 200 hour test
- Three rapid hydrogen embrittlement test methods have been identified for potential use at Hill AFB
 - The Messier-Dowty 16 Hour Hydrogen Embrittlement Test
 - ASTM F 1940 Rapid Hydrogen Embrittlement Test for High Strength Steel Fasteners
 - ASTM F 1624 09 Determination of Hydrogen Embrittlement Threshold Using the ISL (Incremental Step Load) Test Method



Rising Step Load Apparatus



Development of an Accelerated HE Test



- The preferred method to carry out a rapid hydrogen embrittlement test is ASTM F1624 which is as follows:
 - Using the incremental test method in ASTM F 1624, determine the NFS_{F1624} for new – unplated ASTM F 519 Type 1a.1 test specimens. NFS_{F1624} will be lower than NFS_{F8}
 - Qualified rapid hydrogen embrittlement test method (< 20 hrs):
 - Load Type 1a.1 test specimen in Rising Step Load machine and perform step load using ISL conditions (20,5,1) = (20 steps, 5% NFS_{F1624} per step, hold for 1 hour at each step). Determine load where test specimen breaks, this is threshold load P_{th}
 - %NFS = 100 x P_{th} / NFS_{F1624}
 - If %NFS > 90% then process is nonembrittling



Rising Step Load Apparatus



Phase III - Efforts



- Phase III tasks consisted of the following:
 - Waste stream characterization and mitigation
 - Similar wastewater treatment as cadmium.
 - Permitting for hazardous material
 - New source sheets ready to submit
 - Awaiting finalization of the LHE Zn-Ni plating line (i.e. tank size and location)
 - Will apply for Title V air permit when the LHE Zn-Ni plating line is installed
 - Process validation
 - Specification and source control drawings
 - Prototype depot LHE Zn-Ni process line
 - With landing gear components
 - Process orders and Process Orders Document and Display System (PODDS) support
 - Engineering and Program Management Support





- Critical LHE Zn-Ni process parameters were established for the following:
 - Type of Anode
 - Nickel 200
 - Plating fixtures
 - Fixture material can be either stainless (prefered) or carbon steel
 - Current density
 - 40–60 Amps per square foot (ASF)
 - Plating time
 - 10–20 minutes
 - Plating thickness and type of conversion coating
 - Class
 - I minimum of 0.0005" ~ (40 ASF for 20 minutes)
 - II minimum of 0.0003" ~ (40 ASF for 13 minutes)
 - III 0.0001 0.0002" ~ (40 ASF for 10 minutes)
 - Type
 - I No conversion coat
 - II Trivalent or Hexavalent conversion coat





- Critical LHE Zn-Ni process parameters were established for the following:
 - Bath chemistry
 - Requires bi-weekly chemical analysis of the LHE Zn-Ni plating tank using titration
 - Zinc
 - Nickel
 - Carbonate
 - Sodium Hydroxide
 - Requires bi-weekly chemical analysis of the Trivalent CC tank:
 - pH level
 - Cr level
 - Requires quarterly chemical analysis for trace contamination metals for both tanks
 - Agitation requirements
 - Agitation should be sufficient enough to re-circulate the tanks plating solution a minimum of 3 times per hour
 - No air agitation





- Tank chemical maintenance
 - Chemical maintenance for the LHE Zn-Ni process is based on usage and production rates
 - Analysis and adjustment should be performed on an amp-hour used basis, or on a weekly basis
 - Some degree of tracking will be required to establish a historical database of information, which can then be used to recommend regular analysis intervals
 - Specific limits and analysis instructions are provided in the LHE Zn-Ni specification drawing
- Effects of precipitation (carbonate) build up
 - Carbonate formation will decrease the plating efficiency, and perhaps the adhesion performance
 - The best solution is to continually treat out carbonates rather than batch treat in the winter and deal with cyclic carbonate levels and larger replenishment additions
 - A Carbolux[™] system is recommended for treatment of the carbonates
 - It is a mechanism which continually removes solution, precipitates out carbonates, places them in a disposal hopper, and then returns the treated solution back to the plating tank





- Quality compliance testing
 - The following monthly compliance testing is required:
 - Bend to break adhesion coupons per ASTM B571 on plated 1"x 4"x 0.040" coupons (4ea)
 - Neutral salt spray corrosion testing per ASTM B117 on plated 4"x 6" coupons (2ea)
 - Hydrogen embrittlement testing per ASTM F519 on plated Type 1.a1 coupons (4ea)



Phase III Effort Prototype Process Line




Prototype Part Matrix										
Component	Part #									
C-5 MLG Stop Plate	4G11453-101B									
F-15 MLG Outer Cylinder	68A412702-1001/1002									
B-1 MLG Axle	1881B85									
F-15 MLG Lower Drag Brace	68A410792-2001									
A-10 MLG Torque Arm	19046-1									
F-16 NLG Inner Cylinder	2007644-103									
C-5 MLG Rotation Collar	4G13565-101A/-101B									
A-10 NLG Axle	18800-3									



Phase III Effort Prototype Parts








A-10 NLG Axle

A-10 MLG Torque Arm



Phase III Effort Prototype Parts








Phase III Effort Prototype Parts









F-15 MLG Cylinder


F-16 NLG Inner Cylinder

F-15 MLG Lower Drag Brace



Phase III Effort Prototype Anode Design






C-5 MLG Rotation Collar



Phase III Effort Prototype B-1 Bushing





Plating B-1 Bushings LHE Zn-Ni




Plated LHE Zn-Ni B-1 Bushings



Phase III Effort Proposed Prototype Plating Line







Specification Drawing




I AP	PLICA	TIC)N								RI	EVΙ	SI	ONS	5						
NEXT AS			SED	ON		RE	V		DI	ESCR					Т	D	ATE	Т	APF	PROV	/ED
\sim		(<i>F</i>	VC N	ИLG)													工			
DIS CR RE WA TH EX VIC DIS	STRIBUTION STRIBUTION ITICAL TEFERRED ARNING IS DOCUMENT COLLATIONS SEMINATION 161-204.	MENT	CON OLAC THESE	TAIN TEEX	ED TO (DAT 7 SC NS TE TITLE (POR	E-TB MS/G ECHN 22, U	IICAL	DATA SEC 2	WHO:	SE EX	FOR 56. POR 2.) OF SEVE	T IS F	REST RIMI	RICT IVE (TED I	SHA BY THER 12 ALTIE	HE AF 2470. ES.	RMS			
	STRUCTI	ON N	OTICE	F 48																	
DIS	R UNCLA SCLOSUR	SSIFI	ED. L	IMIT	ED D	REC	MEN ONS	S, DE	STRO ION C	Y BY	ANY I	METI	HOD ENT.	THAT	T WIL	L PR	(EVE	NT		2	
DIS	R UNCLA SCLOSUR	SSIFI	ED. L	IMIT	ED D	REC	MEN' ONS	S, DE	STRO ION C	Y BY	ANY DO	METI CUM	HOD ENT.	THA	r WIL	L PR	REVE	NT -	-	-	-
DIS	CLOSUR	SSIFI	ED. L	IMIT	ED D	REC	MEN' ONS	S, DE RUCT	ION	Y BY	DO	CUM	ENT.						12	-	-
DIS	REV	SSIFI	ED. L	IMIT	ED D	-	MEN ONS	TS, DE TRUCT	ION C	Y BY .	DO	CUM	ENT.						12		0
REV STATUS	REV SHEET	SSIFI	ED, L	TEN	ED D	REC	MEN' ONS	RUCT	ION C	-	- DO	-	ENT.	9	-	-	-	-			
DIS	REV SHEET REV	SSIFI	ED, L	TEN	- C	REC	MEN' ONS	RUCT		-	- DO	-	ENT.	9	-	-	-	-			
REV STATUS	REV SHEET REV SHEET	SSIFI E OF	ED, L	TEN	T OR	-	MEN' CONS'	TRUCT	·	-	- DO	-	ENT.	9	-	-	-	12	14		
REV STATUS	REV SHEET REV SHEET REV	SSIFI E OF	ED, L CON	IMIT	OR	-	-				- -	- -		0		2			12		0
DIS REV STATUS	REV SHEET REV SHEET REV SHEET REV SHEET REV	SSIFI E OF	ED, L CON	TEN 3	- 4	5	- - 6	7		- - - 10	- - - 11	- - 12	- - - 13	14	- 15	- 16	- 17	- 18	- 19	- 20	21
REV STATUS	REV SHEET	SSIFI E OF	ED, L CON	TEN 3	- 4	5	- - 6			- - - 10	- - - 11	- 12 - S•	- - 13 -	- - 14 -	- 15 - FC	- - 16 -	- 17 -	- 18	- 19	- 20 -	21
DIS DIS DISCONTINUO DE LESS OTHERNIS DISCONTINUO DI LESS OTHERNIS DISCONTINUO DI LEGIS ANE FRACTIONES DECLI DI LEGIS DELL'ANTICONES DECLI DI L'ANTICONES DECLI DI L'ANTICONE DECLI DI L'ANTICONES DECL	REV SHEET	SSIFI E OF 1 - 22 DFTS CHKR MATL PROJ	ED, L CON'	- 3	4 -	5	- - 6 -			- - 10	- - - - - - - - - - - -	- 12 - Sp	- 13 - A	- - 14 -	- 15 - FC	- - 16 - DRC	- 17 -	- - 18 -	- 19	- 20 -	21

www.ES3inc.com • 1669 E. 1400 S • Clearfield, UT 84015 (801) 926-1150 • fax (801) 926-1155



Source Control Drawing





www.ES3inc.com ● 1669 E. 1400 S ● Clearfield, UT 84015 (801) 926-1150 ● fax (801) 926-1155



Questions





www.ES3inc.com • 1669 E. 1400 S • Clearfield, UT 84015 (801) 926-1150 • fax (801) 926-1155